

**SHORELINE CERTIFICATION: PORTION OF TMK (2) 3-3-001:001**



**PHOTO 1: SHORELINE AT BOTTOM OF DEBRIS PILE  
DATE: 12 NOON AUGUST 3, 2012**



**PHOTO 2: SHORELINE AT BOTTOM OF DEBRIS PILE  
DATE: 12 NOON AUGUST 3, 2012**

**SHORELINE CERTIFICATION: PORTION OF THK(2)3-3-001:001**



**PHOTO 3: LATH 5 AT END OF DEBRIS PILE  
FROM LATH 5 TO LATH 1 SHORELINE AT ROOTS OF  
VEGETATION AT TOP BANK  
DATE: 12 NOON AUGUST 3, 2012**



**PHOTO 4: SHORELINE AT ROOTS OF VEGETATION AT TOP BANK  
DATE: 12 NOON AUGUST 3, 2012**

**SHORELINE CERTIFICATION: PORTION OF TMK(2) 3-3-001:001**



**PHOTO 5: SHORELINE AT TOP OF BANK (BARREN AREA BETWEEN LATHS 3 AND 4 DUE TO A WOODEN PLATFORM THAT WAS REMOVED)  
DATE: 12 NOON AUGUST 3, 2012**



**PHOTO 6: SHORELINE AT TOP OF BANK  
REMOVED WOODEN PLATFORM BLOCKED SUNLIGHT  
TO VEGETATION  
DATE: 12 NOON AUGUST 3, 2012**

**SHORELINE CERTIFICATION: PORTION OF TMK(2) 3-3-001:001**



**PHOTO 7: SHORELINE AT ROOTS OF VEGETATION AT TOP OF BANK  
DATE: 12 NOON AUGUST 3, 2012**



**PHOTO 8: SHORELINE AT ROOTS OF VEGETATION AT TOP OF BANK  
DATE: 12 NOON AUGUST 3, 2012**

SHORELINE CERTIFICATION: PORTION OF TMK(2) 3-3-001:001



PHOTO 9: SHORELINE AT ROOTS OF VEGETATION AT TOP OF BANK  
DATE: 12 NOON AUGUST 3, 2012



PHOTO 10: SHORELINE AT ROOTS OF VEGETATION AT TOP OF BANK  
DATE: 12 NOON AUGUST 3, 2012