



Photo # 1. Taken at the S-E corner of property looking southeasterly. "Shoreline" follows the seaward face of CRM wall.




Photo # 2. Taken at the S-E corner of property looking westward. "Shoreline" follows the seaward face of CRM wall.




Photo # 3. Taken at south side of property looking easterly. "Shoreline" follows the seaward face of CRM wall.



Photo # 4, Taken at south side of property looking easterly. "Shoreline" follows the seaward face of CRM wall which is partially hidden by vegetation.



Photo # 5. Taken at the southend of property looking northward. "Shoreline" follow the seaward face of CRM wall as partially hidden by the Naupaka vegetation.



Photo # 6. Taken at the southend of property @ survey station looking northward. "Shoreline" follows the seaward face of CRM wall as hidden by the Naupaka vegetation.




Photo # 7. Taken at southwest corner of property looking northwesterly. "Shoreline" follows the sea face of CRM wall and vegetation line.



Photo # 8. Taken at the southwest corner of property looking southeasterly. "Shoreline" follows vegetation line.



Photo # 9. Taken at near mid section of the shoreline boundary looking southeasterly. "Shoreline" follows vegetation line and seaward face of CRM wall which is hidden.



Photo # 10. Taken at near mid-section of shoreline boundary looking northward. "Shoreline" follows vegetation line.



Photo # 11. Taken at near mid-section of shoreline boundary looking northward. "Shoreline" follows vegetation line.



Photo # 12. Taken at near mid-section of shoreline boundary looking southward. "Shoreline" follows vegetation line.



Photo # 13. Taken at near northwest corner of property looking southward. "Shoreline" follows vegetation line.



Photo # 14. Taken at near northwest corner of property looking northeasterly. "Shoreline" follows the vegetation line and top of bank (hidden by the Naupaka vegetation).




Photo # 15. Taken at near northwest corner of property looking southward. "Shoreline" follows vegetation line.



Photo # 16. Taken at near northwest corner of property looking northward. "Shoreline" follows top of bank hidden by vegetation line.




Photo # 17. Taken at northwest corner of property looking southward. "Shoreline" follows top of bank which is hedden by vegetation line.



Photo # 18. Taken at northwest corner of property looking southward. "Shoreline" follows top of bank which is covered by the vegetation.