



Photo # 1. Taken on 8/27/13 at southwest corner of Lot 47-A looking southward. Shoreline follows the upper reaches of waves at normal condition.



Photo # 2. Taken on 8/27/13 at southwest corner of Lot 47-A looking northward. Shoreline follows the upper reaches of waves at normal condition.




Photo # 3. Taken on 8/27/13 at southwest corner of Lot 47-A looking southward. Shoreline follows the upper reaches of wave at normal condition.



Photo # 4. Taken at mid section of Lot 47-A looking eastward. Shoreline follows the upper reaches of waves at normal condition



Photo # 5. Taken on 8/27/13 at mid section of Lot 47-A looking northward. Shoreline follows the upper reaches of waves at normal condition.




Photo # 6. Taken on 8/27/13 at northwest corner of Lot 47-A looking southward. Shoreline follows the upper reaches of waves at normal condition.



Photo # 7. Taken on 8/27/13 at northwest corner of Lot 47-A looking northward. Shoreline follows the upper reaches of waves at normal condition.



Photo # 8. Taken on 8/27/13 at northwest corner of Lot 47-A looking southward. Shoreline follows the upper reaches of waves at normal condition.



Photo # A Taken 9/17/13 at Northwest of property looking northwestward. Shoreline follows the toe of CRM wall.



Photo # B. Taken 9/17/13 at northwest corner of property looking eastward. Shoreline follows the toe of CRM wall.



Photo # C. Taken on 9/17/13 at mid section of property looking northwestward. Shoreline follows the toe of CRM wall.




Photo # D. Taken on 9/17/13 at mid section of property looking eastward. Shoreline follows the toe of CRM wall.



Photo # E. Taken on 9/17/13 at southwest corner of property looking northward. Shoreline follows the toe of CRM wall.



Photo # F. Taken on 9/17/13 at southwest corner of property looking eastward. Shoreline follows the toe of CRM wall underneath the concrete walkway.



Photo # G. Taken on 9/17/13 at southwest corner of property southward. Shoreline follows the edge of concrete walkway running southward across the Bougainvillea plants.



Photo # H, Taken on 9/17/13 at northwest corner of Lot 41-A looking northward. Shoreline follows the toe of Bougainvillea mound.