

SHORELINE CERTIFICATION SURVEY OF  
 LOT 11, VACATIONLAND HAWAII  
 (FILE PLAN 814)  
 L. C. AW. 8559 APANA 5  
 KAPOHO, PUNA  
 ISLAND OF HAWAII, HAWAII



PHOTO A



PHOTO B

NOTES:

1. The shoreline was determined by the evidence of the highest wash of the waves at 3:15 pm on 3 July 2012, a high tide event of 3.14 feet.
2. The reason for establishing this shoreline is to determine the building setback for Lot 11.
3. Applicant/Owner: Nicholas Dilonardo  
 4364 West Point Loma Blvd. Apt. G  
 San Diego, CA 92107
4. The photographs were taken at 1:00 pm on 14 June 2012 and at 9:00 am 5 July 2012.




This work was prepared by me or under my direct supervision

*Richard Sunden*  
 Richard Sunden  
 Licensed Professional Land Surveyor  
 License Number 12746

Date: 26 July 2012  
 Drawing: JOB9913photoR1.dwg  
 TMK: (3) 1-4-67:11

The Independent Hawaii Surveyors, LLC

P.O. BOX 577  
 Hilo, HI 96721  
 Phone 808 959-0360  
 FAX 808 959-0353  
 info@hawaiiboundary.com



SHORELINE CERTIFICATION SURVEY OF  
 LOT 11, VACATIONLAND HAWAII  
 (FILE PLAN 814)  
 L. C. AW. 8559 APANA 5  
 KAPOHO, PUNA  
 ISLAND OF HAWAII, HAWAII



PHOTO C



PHOTO D

NOTES:

1. The shoreline was determined by the evidence of the highest wash of the waves at 3:15 pm on 3 July 2012, a high tide event of 3.14 feet.
2. The reason for establishing this shoreline is to determine the building setback for Lot 11.
3. Applicant/Owner: Nicholas Dilonardo  
 4364 West Point Loma Blvd. Apt. G  
 San Diego, CA 92107
4. The photographs were taken at 1:00 pm on 14 June 2012 and at 9:00 am 5 July 2012.




This work was prepared by me  
 or under my direct supervision

*Richard Sunden*  
 Richard Sunden  
 Licensed Professional Land Surveyor  
 License Number 12746

Date: 26 July 2012  
 Drawing: JOB9913photoR1.dwg  
 TMK: (3) 1-4-67:11

The  
 Independent  
 Hawaii  
 Surveyors, LLC

P.O. BOX 577  
 Hilo, HI 96721  
 Phone 808 959-0360  
 FAX 808 959-0353  
 info@hawaiiboundary.com



SHORELINE CERTIFICATION SURVEY OF  
 LOT 11, VACATIONLAND HAWAII  
 (FILE PLAN 814)  
 L. C. AW. 8559 APANA 5  
 KAPOHO, PUNA  
 ISLAND OF HAWAII, HAWAII



PHOTO E



PHOTO F

NOTES:

1. The shoreline was determined by the evidence of the highest wash of the waves at 3:15 pm on 3 July 2012, a high tide event of 3.14 feet.
2. The reason for establishing this shoreline is to determine the building setback for Lot 11.
3. Applicant/Owner: Nicholas Dilonardo  
 4364 West Point Loma Blvd. Apt. G  
 San Diego, CA 92107
4. The photographs were taken at 1:00 pm on 14 June 2012 and at 9:00 am 5 July 2012.



This work was prepared by me  
 or under my direct supervision

*Richard Sunden*  
 Richard Sunden  
 Licensed Professional Land Surveyor  
 License Number 12746

Date: 26 July 2012  
 Drawing: JOB9913photoR1.dwg  
 TMK: (3) 1-4-67:11

17x11

The  
 Independent  
 Hawaii  
 Surveyors, LLC

P.O. BOX 577  
 Hilo, HI 96721  
 Phone 808 959-0360  
 FAX 808 959-0353  
 info@hawaiiboundary.com

