


Established 1969

PHOTOGRAPH LOG
FOR
SHORELINE CERTIFICATION
Tax Map Key: (2) 3-8-02: 25

Spreckelsville, Wailuku, Maui, Hawaii

June 19, 2012



WARREN S. UNEMORI ENGINEERING, INC.
Civil and Structural Engineers – Land Surveyors
Wells Street Professional Center – Suite 403
2145 Wells Street
Wailuku, Maui, Hawaii 96793



Photo No. 1
Looking at Point A
Bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 2
From Point A to Point B
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 3
From Point B to Point C
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 4
From Point C to Point D
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 5
From Point D to Point E
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 6
From Point E to Point F
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 7
From Point F to Point G
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 8
From Point G to Point H
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 9
From Point H to Point I
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 10
From Point I to Point J
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 11
From Point J to Point K
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12




Photo No. 12
From Point K to Point L
Along bottom bank/ Vegetation line

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 13
From Point L to Point M
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12



Photo No. 14
From Point M to Point L
Along bottom bank

TMK: (2) 3-8-02: 25
10:00 to 11:00 am
6/1/12