SHORELINE CERTIFICATION: TMK (2) 3-8-002:051

PHOTO 1: LOOKING WEST AT LATHS 1 AND 2. LATH 2 MARKING MAG NAIL IN BOULDER AT NORTHWEST (RECORD) BOUNDARY CORNER. SHORELINE AT EDGE OF SEAWALL AND ACROSS BOULDERS
PHOTO: 11 AM SEPT. 11, 2012

PHOTO 2: LOOKING WEST FROM LATH 3 MARKING EDGE OF SEAWARD FACE OF UPPER LEVEL OF SEAWALL.
PHOTO: 11 AM Sept. 11, 2012

SHORELINE CERTIFICATION : TMK (2) 3-8-002 : 051

PHOTO 3: LOOKING WEST FROM LATH 4. SHORELINE AT EDGE OF SEAWALL. PHOTO TAKEN 11 AM SEPT. 11, 2012

PHOTO 4: LOOKING WEST FROM LATH 5. SHORELINE AT EDGE OF SEAWALL. PHOTO TAKEN 11 AM SEPT. 11, 2012

SHORELINE CERTIFICATION: TMK (2) 3-8-002 : 051

PHOTO 5: LOOKING WEST AT LATH 6. SHORELINE AT EDGE OF SEAWALL. PHOTO TAKEN 11 AM SEPT 11, 2012

PHOTO 6: LOOKING EAST FROM LATH 6. STARTING AT LATH 7
SHORELINE AT SEAWARD EDGE OF LOWER LEVEL OF THE SEAWALL
PHOTO TAKEN: 11 AM SEPT. 11, 2012

SHORELINE CERTIFICATION: TMK (2) 3-8-002:051

PHOTO 7: LOOKING EAST AT LOWER LEVEL OF SEAWALL. SHORELINE AT SEAWARD EDGE OF WALL. PHOTO: 11 AM Sept. 11, 2012

PHOTO 8: LOOKING EAST FROM LATH 9. SHORELINE AT SEAWARD EDGE OF LOWER LEVEL OF SEAWALL PHOTO: 11 AM Sept. 11, 2012

SHORELINE CERTIFICATION: TMK (2) 3-8-002:051

PHOTO 9: LOOKING EAST FROM LATH 9. SHORELINE AT SEAWARD EDGE OF SEAWALL. PHOTO: 11 AM Sept 11, 2012

PHOTO 10: LOOKING EAST AT FIRST OF 3 CONCRETE BUTTRESSES SHORELINE AT EDGE OF SEAWALL AND BUTTRESSES PHOTO: 11 AM SEPT. 11, 2012

SHORELINE CERTIFICATION: TMK (2) 3-8-002 : 051

PHOTO 11 : LOOKING SOUTHWEST AT LAST OF 3 CONCRETE BUTTRESSES SHORELINE AT EDGE OF SEAWALL AND EDGE OF BUTTRESSES
PHOTO : 11 AM Sept. 11, 2012

PHOTO 12 : LOOKING SOUTHWEST AT NORTHEAST CORNER OF PARCEL 51 SHORELINE AT EDGE OF SEAWALL AND BUTTRESSES
PHOTO : 11 AM Sept. 11, 2012